

PERMITTED ASTs

Owner ID	24195	24195	24195	24195	24195	24195
Facility ID	40348	43744	44941	43553	43553	44517
Tank #	001	001	A001	2	3	1
Status of Tank	In use	In use	in use	In use	In use	in use
Exempt?	No	No	no	No	No	No
Tank Material	Steel	Steel	steel	Steel	Steel	
Year Installed	1992	2001	2012	2006		2002
Capacity (Gal)	1000	12000	3000	3000	3000	1100
Product Stored	Gas (incl alcohol)	Aviation Gas 100 LL	Diesel	Used Oil	Used Oil	diesel
CAS #	8006-61-9	86290-81-5				
Physical/Health Hazards	F, C, A	F, C, A				
Clean/Empty?						
Spill Protection			Double wall	Double Wall	Double Wall	
Location	Salina @ Facilities	Salina	Ashland Ag Farm	Manhattan-Ag Research Farm	Manhattan-Ag Research Farm	Ackert Hall - generator
Owner/Operator	Rene Doherty	Kurt Barnhart	Vernon Schaffer	Vernon Schaffer	Vernon Schaffer	Ed Heptig
email	kkary@ksu.edu		vas@ksu.edu	vas@ksu.edu	vas@ksu.edu	baml@ksu.edu
Department	Facilities	Aviation, 103 AERO CTR	Agriculture	Agriculture	Agriculture	Facilities
Street Address	2409 Scanlan Ave.	1948 Beechcraft Rd.	2850 E 32nd Ave	2200 Kimball Ave.	2200 Kimball Ave.	Denison Ave. & Claflin Rd.
Phone	826-2947	826-2972	532-6115	532-6115	532-6115	2-1700

Owner ID	43586	24195	24195	24195	24195	24195
Facility ID	44021	24195	24195	44361	44361	44358
Tank #	1	001	002	001	002	001
Status of Tank	In use	In use	In use	In use	In use	In use
Exempt?	No	No	No	No	No	No
Tank Material	steel					
Year Installed	2000	1999	2004	2006	2006	2006
Capacity (Gal)	2,000	19550	19550	730	10000	1000
Product Stored	Ethanol E-85	Diesel clear	Fuel Oil No. 2	Potassium hydroxide	Diesel Clear	Diesel Dyed Red
CAS #	64-17-5	68476-34-6	68476-34-6	1310-58-3	68476-34-6	68476-34-6
Physical/Health Hazards	F,C,A	F, C, A	F, C, A	A	F,C,A	F,C,A
Clean/Empty?						
Spill Protection	double-walled	double-walled	double-walled		double-walled/dike	double walled
Location	Motor Pool	Manhattan - Power Plant	Manhattan - Power Plant	BRI	BRI	AS&I
Owner/Operator	Kansas Corn Commission, Sue Hardman	Delvin Winfough	Delvin Winfough	Bryan Phillips	Bryan Phillips	Ron Pope
email				bryanp@ksu.edu	bryanp@ksu.edu	rvpope@ksu.edu
Department		Facilities	Facilities	BRI	BRI	AS&I, WB 218
Street Address		N. 17th St.	N. 17th St.	1940 Denison Ave	1940 Denison Ave	2900 College Ave
Phone	785-448-6922	532-1732	532-1732	532-3246	532-3246	539-6621

Owner ID	24195	24195	24195	24195	24195	24195
Facility ID	44348	44348	44516	44348	43340	
Tank #	A002	A003	A001		A001	
Status of Tank	In use	In use	In use	In use	In use	
Exempt?	No	No	No	No	no	
Tank Material	steel	steel	Steel		steel	
Year Installed	2008	2013	2007	2005	????	
Capacity (Gal)	1000	676	1250	850	2000	
Product Stored	Diesel	Diesel	Diesel	Potassium hydroxide	Diesel	
CAS #	68476-34-6	68476-34-6	68476-34-6	1310-58-3	68476-34-6	
Physical/Health Hazards	F, C, A	F, C, A	F, C, A	C, A	F,C,A	
Clean/Empty?						
Spill Protection	Double-walled	Double-walled	Double-walled		Double-walled	
Location	Mosier Hall - generator	Mosier Hall - generator	Coles Hall - generator	D112 Mosier	Lafene	
Owner/Operator	Allan Leikam	Allan Leikam	Allan Leikam	Leah Hanzlicek	Delvin Winfough	
email	aleikam@vet.k-state.edu	aleikam@vet.k-state.edu		lhanzlic@ksu.edu	dwinfoug@ksu.edu	
Department	Vet Med	Vet Med	Vet Med	DMP	Facilities	
Street Address	1700 Denison Ave	1700 Denison Ave	1700 Denison Ave	1700 Denison Ave	1105 Sunset Ave.	
Phone	2-6840	2-6840	2-6840	2-4399	2-1731	

PERMITTED USTs

Owner ID	24195	24195	24195	24195	24195	
Facility ID	30391	30388	30388	30389	30389	
Tank #	U027	U028	U029	U030	U031	6
Status of Tank	In use	In use	In use	In use	In use	Removed
Year Installed	1987	1991	1991	1995	1995	1983
Tank Material	Fiberglass reinforced plastic	Steel	Steel	Fiberglass	Fiberglass	
Capacity (Gal)	550	2,000	2,000	12,000	4,000	1,000
Product Stored	Diesel	Gas (incl alcohol)	Diesel	Gas (E-10)	Diesel	Diesel
CAS #	68476-34-6	8006-61-9	68476-34-6	8006-61-9	68476-34-6	
Physical/Health Hazards	F, C, A					
Tank Release Detection	MTG	TT, ATG	TT, ATG	ATG	ATG	
Dispenser Type	Safe suction	Safe suction	Safe suction	Pressure	Pressure	
Shutoff/Alarm/FR/LM				ALM	ALM	
Line Release Detection						
Financial Responsibility	SI	SI	SI	SI	SI	
Spill Protection						
Location	Bramlage	Ag Research-Kimball	Ag Research-Kimball	Dykstra	Dykstra	
Owner/Operator	Terry Pittman	Vern Schaffer, Agronomist	Vern Schaffer, Agronomist	Kris Fulkerson	Kris Fulkerson, Procurement Officer	
email	terence@ksu.edu	vas@ksu.edu			kst8cat@ksu.edu	
Phone	7600	6115	6115	1765	1765	
Other info	137 Bramlage	Throckmorton	Throckmorton	Dykstra	Dykstra	
Department	Athletics	Agronomy	Agronomy	Facilities	Facilities	
Street Address	1800 College Ave	2200 Kimball Ave	2200 Kimball Ave	1700 Claflin Rd	1700 Claflin Rd	
Required Testing		Cathodic protection test required every 3 years.				
		Test dates:	2/11/2009			
			Done Feb 2012			
			Due 2015			
Trained personnel/date:	Terry P/May08/Aug2014 A/B00000395 Micael Barton/Aug2014 A/B00004216	Stan R/May-08 Fred P/May-08	Vern S./May 08 Mitch R/ May 08	Sarah Davis/spring 2012/AB00003555	Kris Fulkerson/spring 2012/ AB00003542	Kelly Greene/Aug2014/ AB00000344

Experiment Farms

Owner ID	44294	44294	44294	40669	40669	40669
Facility ID	44294	44294	44294	40669	40669	40669
Tank #	A001	A002		A001	A002	
Exempt?			Yes			Yes
Tank Material						
2nd Containment	Concrete	Concrete	None	Concrete	Concrete	None
Year Installed						
Capacity (Gal)	1000	2000	300	1000	1000	1000
Product Stored	Gasoline	Diesel	Used Oil	Gasoline	Diesel	Used Oil
CAS #						
Physical/Health Hazards						
Other info						
Location	Colby	Colby	Colby	Garden City	Garden City	Garden City
Owner/Operator	Dan Foster	Dan Foster	Dan Foster	Jeff Elliott	Jeff Elliott	Jeff Elliott
Dept						
Phone	785-462-6281	785-462-6281	785-462-6281	620-276-8286	620-276-8286	620-276-8286

Owner ID	27256	27256	27256	40885	40885	40885
Facility ID	27256	27256	27256	40885	40885	40885
Tank #	A002	A001		A001	A001	
Exempt?			Yes			Yes
Tank Material						
2nd Containment	Concrete	Concrete	None	Concrete	Concrete	None
Year Installed						
Capacity (Gal)	2000	2000	300	1000	1000	100
Product Stored	Gasoline	Diesel	Used oil	Gasoline-unlead, reg	Diesel-dyed off road	Used Oil
CAS #						
Physical/Health Hazards						
Other info						
Location	Hays	Hays	Hays	Tribune	Tribune	Tribune
Owner/Operator	Joseph Becker	Joseph Becker	Joseph Becker	Alan Schlegel	Alan Schlegel	Alan Schlegel
Dept						
Phone	785-625-3425	785-625-3425	785-625-3425	620-376-4761	620-376-4761	620-376-4761

NON-PERMITTED ASTs

Facility ID Tank #	43909 001	40348 002	40348 003	40348 004	40348 005	
Status of Tank Exempt?	In use Yes	In use Yes	In use Yes	In use Yes	In use Yes	
Tank Material		Steel	Steel	Steel	Steel	Steel
Year Installed	2002	1900	1900	1900	1900	1998
Capacity (Gal)	500	550	550	550	550	660
Product Stored	Gas (incl alcohol)	Gas (incl alcohol)	Diesel	Used oil	Used oil	Diesel
CAS #	8006-61-9	8006-61-9	68476-34-6			
Physical/Health Hazards	F, C, A	F, C, A	F, C, A	F, C, A	F, C, A	
Spill Protection	mannattan - Facilities/ Grounds	Salina @Facilities	Salina @Facilities	Salina @Facilities	Salina - @Facilities	AS&I Farm Shop
Location						
Owner/Operator	Jacque Toburen	Renee Doherty	Renee Doherty	Renee Doherty	Renee Doherty	Ron Pope
email	tobujaa@ksu					rvpope@ksu
Dept		Facilities	Facilities	Facilities	Facilities	AS&I Farm Shop
Phone	532-1795	826-2947	826-2947	826-2947	826-2947	532-5404

Facility ID Tank #				where are these???? ???????	???????	
Status of Tank Exempt?	Yes	Yes	Yes	Yes	Yes	Yes
Tank Material	Steel	Steel	Steel	Steel	Steel	
Year Installed	?	?	1999	1992	1992	not yet
Capacity (Gal)	250	200	200	750	1,000	500
Product Stored	Unleaded Gas	Used Oil	Diesel	Aviation fuel	Diesel	Diesel
CAS #						
Physical/Health Hazards						
Spill Protection						
Other info	Mobile tank	Mobile tank				
Location	Motorpool	Motorpool	Vet Med	Salina	Salina	AMI
Owner/Operator	Butch (Gerald) Buch	Butch (Gerald) Buch	Dennis Ahlvers	Allan Leikam	Allan Leikam	Scott Case
Dept	Facilities	Facilities	Vet Med	Facilities	Facilities	
Phone	532-6382	532-6382	532-6840	826-2947	826-2947	

Facility ID Tank #	44941			
Status of Tank Exempt?	in use yes			
Tank Material	steel			
Year Installed	2012	2008	2008	
Capacity (Gal)	520	560	560	
Product Stored	gasoline	gas	diesel	
CAS #				
Physical/Health Hazards				
Spill Protection		diked	diked	
Location	Ashland Ag Farm	Olathe	Olathe	
Owner/Operator	Vern Schaffer			
email	vas@ksu.edu			
Dept	Agronomy			
Phone	532-6115			

NON-PERMITTED USTs

Owner ID				west tank	east tank	
Facility ID			30387	30387	30387	
Tank #	014	15	9	32	33	1
Status of Tank						
Year Installed	1967 Removed 2012	1967 Removed 2012	1979	1997	1997	1951
Tank Material	Steel	Steel	Steel	Steel	Steel	
Capacity (Gal)	1,000	1,000	1,000	1,000	1,000	228,952
Product Stored	Gas (incl alcohol)	Diesel	Diesel	Gas (incl alcohol)	Gas (incl alcohol)	#6 fuel oil
CAS #						
Physical/Health Hazards						
Tank Release Detection						
Dispenser Type						
Shutoff/Alarm/FR/ALM				conv. Suction	conv. Suction	
Line Release Detection						
Financial Responsibility						
Spill Protection				spill bucket	spill bucket	
Location	Ashland	Ashland	AS&I	2900 College	2900 College	PowerPlant
Owner/Operator				Russel Gottlob	Russel Gottlob	
Phone				539-6621	539-6621	
Department				AS&I	AS&I	